

Genuine Spicer® S110 Ring and Pinion Kit Content Change

Date: **Tuesday, April 14, 2020**

To: **All Dana Aftermarket Group Spicer® Heavy Axle Customers**

Affected Models: **S110**

Once stock is exhausted of the below “old” ring and pinion kits in the chart, customers will need to order the “new” ring and pinion kit part numbers. The new kits will NOT contain wheel differential bearings. This is the only difference. For kits containing wheel differential bearings for this model, please reference bulletin HAXL-PNI-106.

Old Part #	New Part #	New Description	Notes
511831	10005947	Ring and Pinion Kit (133968) 373	Bearings Removed
511832	10005948	Ring and Pinion Kit (133969) 391	Bearings Removed
511833	10005949	Ring and Pinion Kit (133970) 410	Bearings Removed
511835	10005951	Ring and Pinion Kit (133972) 456	Bearings Removed
511836	10005953	Ring and Pinion Kit (133973) 478	Bearings Removed
511838	10005956	Ring and Pinion Kit (133975) 513	Bearings Removed
511840	10005958	Ring and Pinion Kit (133977) 557	Bearings Removed
511841	10005959	Ring and Pinion Kit (133978) 586	Bearings Removed
511842	10005960	Ring and Pinion Kit (133979) 614	Bearings Removed
511843	10005961	Ring and Pinion Kit (133980) 650	Bearings Removed
512277	10005950	Ring and Pinion Kit (133971) 430	Bearings Removed
512279	10005957	Ring and Pinion Kit (133976) 538	Bearings Removed
511837	10005955	Ring and Pinion Kit (133974) 488	Bearings Removed

If you need additional information, please contact your Dana Aftermarket representative. Thank you for your continued support of Dana Aftermarket products!



Courtney McGuire
Associate Product Manager
Spicer® Heavy Axle Products

SpicerParts.com

Dana Aftermarket Group
PO Box 1000 Maumee, Ohio 43537
Warehouse Distributors: 1.800.621.8084
OE Dealers: 1.877.777.5360

Follow SpicerParts     